


# Seam Finish: Neatening raw edges with overlock substitute stitches


Many machines, in particular the electronic machines have these stitches. There are two overcast or overlock feet options, Foot M and Foot C. It is important to use the appropriate stitch with the corresponding foot.

With our samples we used:

Foot M with this stitch:  
(This foot has three metal bars)



Foot C with this stitch:  
(This foot has two metal bars & a brush)



## Method:

- Stitch a seam using a 1.5cm (5/8") seam allowance
- Using either Foot M or Foot C with their corresponding stitch overcast the raw edges
- Press open the seam